

FLOWMETER 66, <del>1</del>3 37 38 CONDUCTIVITYMETER 36 QE) PH METER FIG.2 
Head
33 FLOWMETER 32  $\infty$ -31 FLOWMETER 7 Ha CONDUCTIVITYMETER PH METER THERMOMETER

2/12


S

Ó


THERMOMETER


THERMOMETER 9 S FLOWMETER 36 36 <u>ლ</u> 38~ CONDUCTIVITYMETER 36 GE GE PH METER Ha FIG.3 32  $\infty$ FLOWMETER 7 H CONDUCTIVITYMETER PH METER THERMOMETER

3 / 12



F1G.5





## FIG.7A




FIG.7B







FIG.7C




## FIG.8



-



:



F.Ignuak " Betonon:




FIG. 118

